

# LIFTING

Lifting points – ready for bolting



**RS**  
Eye bolt



**RM**  
Eye nut

Thread sizes  
**M6 – M48**  
further thread types  
and special lengths  
on request.

see p.116

0.1 t	0.2 t	0.25 t	0.4 t	0.75 t	1 t (0,8 t)	1.5 t	2 t	3 t	4 t	6 t	8 t	type
M6	M8	M10	M12	M14	M16	M20	M24	M30	M36	M42	M48	thread size
1/4"	5/16"	3/8"	7/16"	9/16"	5/8"	7/8"	1"	1 1/4" 1 3/8"	1 1/2"	1 3/4"	2"	$\beta$ number of legs
0.4	0.8	1	1.6	3	4 (3,2)	6	8	12	16	24	32	0° 1
0.8	1.6	2	3.2	6	8 (6,4)	12	16	24	32	48	64	0° 2
0,1	0,2	0,25	0,4	0,75	1 (0,8)	1,5	2	3	4	6	8	90° 1
<p><b>We recommend to use either "VRS-Starpoint" or "VRM-Starpoint eye nut" which can be adjusted to the direction of pull!</b></p>												90° 2
												0-45° 2
												45-60° 2
												unsymmetrical 2
												0-45° 3+4
												45-60° 3+4
<p><b>We recommend to use either "VRS-Starpoint" or "VRM-Starpoint eye nut" which can be adjusted to the direction of pull!</b></p>												unsymmetrical 3+4

() = deviating WLL of the RM